Attorney's Docket No. 62020-1220

PATENT B

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

MADEL Ratent Number: 7,016,569 B2

Issued: March 21, 2006

Name of Patentee: Mule, et al.

Title of Invention:

APR 2 7 2006

Back-Side-Of-Die, Through-Wafer Guided-Wave Optical

Clock Distribution Networks, Methods Of Fabrication Thereof,

and Uses Thereof

Commissioner for Patents P.O. Box 1450 Alexandria, Virginia 22313-1450

Certificate

MAY 9-1 2006

ATTENTION: Decision and Certificate of Correction
Branch of the Patent Issue Division

of Correction

REQUEST FOR CERTIFICATE OF CORRECTION OF PATENT (37 C.F.R. 1.322(a) and 37 C.F.R. 1.323)

1. Attached, in duplicate, is PTO/SB/44 (also Form PTO-1050), with at least one copy being suitable for printing.

NOTE: Form PTO-1050 (or PTO/SB/44), using the column and line number in the printed patent, should be used exclusively regardless of the length or complexity of the subject matter. M.P.E.P § 1485, 7th ed.

NOTE: The patent grant should be retained by the patentee. The PTO does not attach the certificate of correction to the patentee's copy of the patent. The patent grant will be returned to the patentee if submitted. M.P.E.P. § 1485.

2. The errors for which Applicants seek correction pursuant to 37 C.F.R. § 1.322(a) are shown correctly in the application file. The requested corrections are described below.

NOTE: This information should be identified in this request; however, on Form PTO-1050, only the column and line number in the printed patent should be used. M.P.E.P. §1485, 7^{th} ed.

04/28/2006 MWOLDGE1 00000017 7016569

01 FC:1811

100.00 OP

IN THE TITLE

Please amend the title to read:

"BACK-SIDE-OF-DIE, THROUGH-WAFER GUIDED-WAVE OPTICAL CLOCK DISTRIBUTION NETWORKS, METHODS OF FABRICATION THEREOF, AND USES THEREOF"

IN THE SPECIFICATION

Column 5, line 28, delete "1115" and replace with --115--.

3.	It is further noted, pursuant to 37 C.F.R. §1.323, that errors appear in this patent that are of		
	\boxtimes	clerical	
	\boxtimes	typographical	

⊠ minor

nature or character, as more fully described below. Such errors occurred in good faith. Correction thereof does not involve such changes in the patent as would constitute new matter or would require re-examination. A certificate of correction is requested.

4. The exact page and line number where the error occurs in the application file are:

NOTE: This information should be identified in this request, however, on Form PTO-1050, only the column and line number in the printed patent should be used. MPEP §1485.

IN THE ABSTRACT

On line 6 of the Abstract, delete "an" and replace with --a--.

IN THE CLAIMS

Column 15, Claim 21, delete the beginning of the claim "A structure" and replace with -- The structure--.

Column 15, Claim 22, delete the beginning of the claim "A structure" and replace with -- The structure--.

IN THE DRAWINGS

Please replace drawing Sheet 3 of 4 (Fig. 2 and Fig. 3) with the enclosed "Replacement Sheet". A typographical error exists in the reference numerals of Fig. 3. Reference numeral. "297b" on Fig. 3 is incorrect. The Replacement Sheet shows the correct reference numeral "397b".

5.	Please	send	the	Certificate	to:

Name: Scott A. Horstemeyer

Address: Thomas, Kayden, Horstemeyer & Risley, LLP

100 Galleria Parkway, N.W., Suite 1500, Atlanta, GA 30339

o. Please	pay the re	ee of \$100.00,	as required t	Dγ 3 /	CFK	1.20(a)	, as ionows
-----------	------------	-----------------	---------------	--------	-----	---------	-------------

	Enclosed is a check for \$.
\boxtimes	Payment by credit card. Form PTO-2038 is attached in the amount of \$100.00.
	Charge the Deposit Account 20-0778 the sum of . A duplicate of this
	request is attached.

SIGNATURE OF PRACTITIONER

Heather C. Gorman, Reg. No. 42,389

(type or print name of practitioner)

Tel. No.: (770) 933-9500 Thomas, Kayden, Horstemeyer & Risley, LLP

100 Galleria Parkway, N.W., Suite 1750

Atlanta, GA 30339-5948

Customer No.: 24504

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

Patent No.: 7,016,569 B2

Dated:

March 21, 2006

Inventor(s): Mule, et al.

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below

Amend the Title to read: "BACK-SIDE-OF-DIE, THROUGH-WAFER GUIDED-WAVE OPTICAL CLOCK DISTRIBUTION NETWORKS, METHODS OF FABRICATION THEREOF, AND USES THEREOF"

On line 6 of the Abstract, delete "an" and replace with --a--.

Column 5, line 28, delete "1115" and replace with --115--.


Column 15, Claim 21, delete the beginning of the claim "A structure" and replace with -- The structure--.

Column 15, Claim 22, delete the beginning of the claim "A structure" and replace with --The structure--.

MAILING ADDRESS OF SENDER:

THOMAS, KAYDEN, HORSTEMEYER & RISLEY, L.L.P. 100 Galleria Parkway, Suite 1750 Atlanta, Georgia 30339

Patent No.: 6,915,217






FIG. 3

CERTIFICATE OF MAILING

I hereby certify that this correspondence is being deposited with the U.S. Postal Service as first class mail in an envelope addressed to:



ATTN: Certificate of Corrections Branch Commissioner for Patents P.O. Box 1450 Alexandria, VA 22313-1450

on 4/24/2006

Laurie Delesandro

In re Patent of: Mule, et al.

U.S. Patent No: 7,016,569

Issue Date: March 21, 2006

Title: Back-Side-Of-Die; Through-Wafer Guided-Wave Optical Clock Distribution

Networks, Methods Of Fabrication Thereof, and Uses Thereof

Docket No.: 62020-1220

The following is a list of documents enclosed:

Return Postcard
Request for Certificate of Correction

Certificate of Correction (& Original Duplicate)

Credit Card Payment Form

Replacement Sheet (Figs. 2 and 3)